

CREW: 31 WORK ORDER TYPE: PD REPAIR

01-19846-25

ISSUE DATE 01/06/11

Page 1 Of 2

Originator	: RICHARD HOUSTON	Schedule Date	:
Planner	: RICHARD HOUSTON	Priority	: 3C
Drawing No	: 1TGA-M2079	Clearance	: NO
Equip No/Cat	: 1TGA--1 2	Tag Request	:
Project ID	: 1TGA-TRB-1	Text ID	: REBUILD*27113
Shutdown	: N No Shutdown	Frequency	: NOT SCHEDULED
Ref No	:	Last Reading	: No Reading

Date Completed: \_\_\_\_\_ Failure Code: \_\_\_\_\_

Completed By : \_\_\_\_\_ Signature : \_\_\_\_\_

Accepted By : Signature :

**\*\* Delay Codes Legend \*\***

W=Whse    C=CrSp    T=Tag    TL=Tool    P=Plan

**\*\* Record Time Daily \*\***

### Delays

Step	Job Scope	MN	DY	Safety and Additional Information
------	-----------	----	----	-----------------------------------

Emp No	Date	Hours	Code/Hrs
--------	------	-------	----------

1 INSPECT AND REBUILD TURBINE CONTROL ROTOR 1 1  
STEADY BEARING

BEARING SHOULD BE SENT TO G.E. REPAIR SHOP  
OR OTHER QUALIFIED VENDOR FOR REPAIR.  
REFER TO REQUISITION ATTACHED TO THE WORK  
ORDER.

STK NO: 27113  
QTY: 1  
ORIG WO: 01-19846-3  
STK ISSUE: 243382

ITEM DESCRIPTION:  
BEARING, SLEEVE, TURBINE MAIN SHAFT OIL  
PUMP.  
G.E. DRAWING #0514C358G0001, CATALOG  
#43202

\*\* IMPORTANT NOTICE \*\*  
 YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND MUST  
 ENSURE THAT THE REQUIRED PPE IS WORN FOR EVERY  
 JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS  
 CONCERNING THE WORK RULES, SAFETY CODES, OR  
 REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.

Job Feedback/Historical Notes:



**IP7\_005540**

\*\* Work Order Parts List \*\*

Part No	Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd
1	DIRECT			EA			
2	DIRECT	04-33242	10/01/03	EA	0	0	0